

Inspection Report Detail

Multiple dates are available for this VIN. Please choose one:

12-12-2008 ▼

Inspection Summary

Ally Account #:

Customer Name:

Co-Customer:

Inspection Company: Autovin

Inspector ID: 183984

Return Date: 01-26-2008

Inspection Date: 10-06-2008

Condition Grade: 1

Comments: TEST.

Vehicle Information & Photos

VIN: 137PH84336E232861

Year: 2006

Interior Color: Green

Mileage: 3698

Make: Hummer

Exterior Color: Dark Blue

License State/Plate:

Model: H1

Smoker: Yes

Series: N/A Hardtop

None

[Back to top](#)

Dealer Information

Dealer Number: 82235001

Dealer Name: ADESA CALGARY

Contact Name:

Dealer Address: Box 5280 Irricana Rd NE, Airdrie, AB T4B 2T9

Telephone:

[Back to top](#)

Damage Information & Photos

[View Ally Excess Wear Table: US](#) | [Canada \(PDF 46K\)](#)

Chargeable Wear: \$3,597.38

Non-Chargeable Wear: \$100.00

Total Wear: \$3,697.38

Exterior Damage:

Location	Description	Chargeable	Frame Hrs	Paint Hrs	Metal Hrs	Repair Hrs	Part Cost	Total Cost	Image
FENDER PANEL Fender	Dent(s)/ Non-Chargeable	Yes		2.6	1.0			\$180.00	
FENDER PANEL Fender	Dent(s)/ No Paint Damage/ PDR	No					\$50.00	\$50.00	
Front Bumper FRONT BUMPER	Painted Signs Repaint	Yes		2.6				\$130.00	
Hood HOOD PANEL	Dent(s)/ No Paint Damage/ PDR	No					\$50.00	\$50.00	
Rear Bumper BUMPER	Gouge(s) Repair (Entire Bumper)	Yes					\$200.00	\$200.00	
RF Door Panel DOOR PANEL	Dent(s)/ Severe	Yes		2.3		7.5	\$313.69	\$803.69	

Interior Damage:

Location	Description	Chargeable	Frame Hrs	Paint Hrs	Metal Hrs	Repair Hrs	Part Cost	Total Cost	Image
3rd Seat Folding Seat Module	Missing Replace	Yes					\$2,000.00	\$2,000.00	
LF Interior Door INTERIOR TRIM	Broken/ Replace	Yes					\$33.15	\$33.15	
LR Door Interior INTERIOR TRIM	Broken/ Replace	Yes					\$25.54	\$25.54	
Wipers/Washer Motor	Inoperable The wiper motor is not functioning. Le	No							

Other Damage/Charges:

Location	Description	Chargeable	Frame Hrs	Paint Hrs	Metal Hrs	Repair Hrs	Part Cost	Total Cost	Image
ADD FOR Fender	Refinish	Yes				0.5		\$25.00	
Left Frame/ Cosmetic ADD FOR	Refinish	Yes				0.5		\$25.00	

[Back to top](#)

Tire Information & Photos:

Tire	Manufacturer	Tire Size	Tread Depth	Description	Tire Cost	Image
Front-Left	Amstrong	17	10mm	Plugged Sidewall/ Replace	\$175.00	
Front-Right	Amstrong	17	10mm		\$0.00	
Rear-Left	Commander	17	10mm		\$0.00	
Rear-Right	Amstrong	17	10mm		\$0.00	
Spare	Amstrong	17	10mm		\$0.00	

[Back to top](#)

Verified Options & Accessories

Interior:	Exterior:	Mechanical:	Other:
After Market (AM):			

[Back to top](#)